DTC

B17	785
-----	-----

Front Occupant Classification Sensor LH Collision Detection

DESCRIPTION

DTC B1785 is output when the occupant classification ECU receives a collision detection signal sent by the front occupant classification sensor LH when an accident occurs.

DTC B1785 is also output when the front seat RH is subjected to a strong impact, even if an actual accident does not occur.

However, when the occupant classification ECU outputs a collision detection signal, even if the vehicle is not in a collision, DTC B1785 can be cleared by performing the zero point calibration and sensitivity check.

Therefore, when DTC B1785 is output, first perform the zero point calibration and sensitivity check.

DTC No.	DTC Detection Condition	Trouble Area
B1785	 When one of following conditions is met: Front seat RH malfunction Occupant classification ECU malfunction Front occupant classification sensor LH detects large load 	 Occupant classification ECU Front seat RH (Front occupant classification sensor LH)

WIRING DIAGRAM



RS

INSPECTION PROCEDURE



- (a) Turn the ignition switch OFF.
- (b) Disconnect the cable from the negative (-) battery terminal, and wait for at least 90 seconds.

(c) Replace the front seat RH (see page SE-8). HINT:

Perform the inspection using parts from a normal vehicle if possible.



	(b)	Turn the ignition switch OFF. Disconnect the cable from the negative (-) battery terminal, and wait for at least 90 seconds. Replace the occupant classification ECU (see page SI 8).
NEXT 9 PERFO	RM ZERO POINT CALIBRATI	ON
LI	(b) (c)	Connect the cable to the negative (-) battery terminal, and wait for at least 2 seconds. Connect the intelligent tester to the DLC3. Turn the ignition switch ON. Using the intelligent tester, perform the zero point calibration (see page RS-241). OK: COMPLETED is displayed.
NEXT		
10 PERFO	RM SENSITIVITY CHECK	
	(a)	Using the intelligent tester, perform the sensitivity check (see page RS-241). Standard value: 27 to 33 kg (59.52 to 72.75 lb)
NEXT		