DTC	B1795	Occupant Classification ECU Malfunction
DIC	D1795	Occupant classification ECO Manufiction

DESCRIPTION

DTC B1795 is recorded when a malfunction is detected in the occupant classification ECU. Troubleshoot DTC B1771 first when DTC B1771 and B1795 are output simultaneously.

DTC No.	DTC Detection Condition	Trouble Area
B1795	 When one of following conditions is met: The occupant classification ECU receives the ignition switch OFF to ON signal 50 times in a row when a malfunction occurs in the power circuit for the occupant classification ECU (OFF to ON to OFF should be counted as 1 time). Occupant classification ECU circuit malfunction The occupant classification ECU receives a short circuit to ground signal in the passenger side buckle switch circuit for 2 seconds. Occupant classification ECU malfunction 	 Battery ECU-B fuse Floor wire No.2 Front seat inner belt RH Occupant classification ECU

WIRING DIAGRAM



INSPECTION PROCEDURE



	N	G REPAIR OR REPLACE WIRE HARNESS		
ОК				
4 REPLACE OCCUPANT CLASS	IFICA			
	(a) (b) (c)	Turn the ignition switch OFF. Disconnect the cable from the negative (-) battery terminal, and wait for at least 90 seconds. Replace the occupant classification ECU (see page R 392). HINT: Perform the inspection using parts from a normal vehicl if possible.		
NEXT				
5 PERFORM ZERO POINT CALIBRATION				
	(a) (b) (c) (d)	Connect the cable to the negative (-) battery terminal, and wait for at least 2 seconds. Connect the intelligent tester to the DLC3. Turn the ignition switch ON. Using the intelligent tester, perform the zero point calibration (see page RS-241). OK: COMPLETED is displayed.		
NEXT				
6 PERFORM SENSITIVITY CHEC	к			
	(a)	Using the intelligent tester, perform the sensitivity che (see page RS-241). Standard value: 27 to 33 kg (59.52 to 72.75 lb)		
NEXT				