
DTC	B2797	Communication Malfunction No. 1
-----	-------	---------------------------------

DESCRIPTION

This DTC is output when a communication error occurs between the transponder key amplifier and transponder key ECU. Some possible reasons for the communication error are: 1) 2 or more ignition keys are positioned too close together, or 2) noise is occurring in the communication line.

DTC No.	DTC Detection Condition	Trouble Area
DZ/9/	Keys are positioned too close to each other, or noise occurred in communication line	 Key Wire harness Transponder key amplifier Transponder key ECU

WIRING DIAGRAM




1

INSPECTION PROCEDURE

CHECK KEY


(a) Check if the ignition key being used is near other ignition keys. Also, check if the key ring is in contact with the key grip.



B130077

Result:

Result	Proceed to
Key is near other keys and/or key ring is in contact with key grip	A
Key is not near other keys and/or key ring is not in contact with key grip	В



No DTC is output.



NG

