

## W/RECEIVER CONDENSER ASSY

5519K-01

### ON-VEHICLE INSPECTION

#### 1. INSPECT COOLER CONDENSER CORE

- (a) If the fins of the condenser assy (w/ receiver) are dirty, clean them with water and dry them with compressed air.

#### NOTICE:

**Do not damage the fins of the cooler condenser core.**

- (b) If the fins of the condenser assy (w/ receiver) are bent, straighten them using a screwdriver or pliers.

#### 2. INSPECT LEAKAGE OF REFRIGERANT

- (a) Using a halogen leak detector, check the pipe joints for gas leakage.
- (b) Check the tightening torque of the joint if gas leakage is detected in a pipe joint.