

DTC	P0A2B/248	DRIVE MOTOR "A" TEMPERATURE SENSOR CIRCUIT RANGE/PERFORMANCE
------------	------------------	---

DTC	P0A2B/250	DRIVE MOTOR "A" TEMPERATURE SENSOR CIRCUIT RANGE/PERFORMANCE
------------	------------------	---

CIRCUIT DESCRIPTION

Refer to DTC P0A2C (INF 247) on page [05-529](#).

DTC No.	INF Code	DTC Detection Condition	Trouble Area
P0A2B	248	Motor temperature sensor No. 1 malfunction	• Hybrid vehicle motor
P0A2B	250	Motor temperature sensor No. 1 performance problem	• Hybrid vehicle motor

INSPECTION PROCEDURE

If the information (INF) code 248 or 250 is present, replace the hybrid vehicle motor.

HINT:

The motor temperature sensor No. 1 is unavailable as an individual service part. Therefore, when replacing it, the hybrid vehicle motor must be replaced.

REPLACE HYBRID VEHICLE MOTOR ASSY
--