055LZ-09

## SOUND QUALITY IS BAD ONLY WHEN CD IS PLAYED (VOLUME IS TOO LOW)

## **INSPECTION PROCEDURE**

- 1 REPLACE CD WITH ANOTHER AND RECHECK
- (a) Replace the CD with another one and recheck.
  - (1) Check the installation condition of the radio receiver assembly.

OK: Malfunction disappears.



REPLACE RADIO RECEIVER ASSY (SEE PAGE 67-5)

OK

**CD IS FAULTY** 

2004 Prius - Preliminary Release (RM1075U)

Author: Date: 1999