

DTC	P3108/537	LOST COMMUNICATION WITH A/C SYSTEM CONTROL MODULE
------------	------------------	--

CIRCUIT DESCRIPTION

Refer to DTC 3108 (INF 535) on page [05-820](#).

DTC No.	INF Code	DTC Detection Condition	Trouble Area
P3108	537	A/C amplifier malfunction	• A/C amplifier

INSPECTION PROCEDURE

If the information (INF) code is present, replace the A/C amplifier.

REPLACE A/C AMPLIFIER
