


# AIR CONDITIONING AMPLIFIER ASSY REPLACEMENT

55190-01

1. REMOVE INSTRUMENT PANEL FINISH PANEL LOWER CENTER (SEE PAGE 71-13)
2. REMOVE AIR DUCT REAR NO.3 (SEE PAGE 55-17)



3. REMOVE AIR CONDITIONING AMPLIFIER ASSY
  - (a) Disconnect the connector.
  - (b) Remove the 2 screws and then the air conditioning amplifier assy.