

HOW TO PROCEED WITH TROUBLESHOOTING

1 VEHICLE BROUGHT TO WORKSHOP



2 CUSTOMER PROBLEM ANALYSIS (SEE PAGE 05-1984)




3 PROBLEM SYMPTOM CONFIRMATION (SEE PAGE 05-1986)



4 CHECK MULTIPLEX COMMUNICATION SYSTEM (SEE PAGE 05-2549)

(a) Check for DTC outputs.



MULTIPLEX DTC OUTPUTS (PROCEED TO "BODY MULTIPLEX COMMUNICATION SYSTEM")



NO MULTIPLEX DTC (GO TO STEP 5)

5 CIRCUIT INSPECTION (SEE PAGE 05-1998 - 05-2013)



6 REPAIR OR REPLACE



7 CONFIRMATION TEST



END